

Tracking On at 16KHz, 4800RPM, use Hysteresis Operation(Prior art)




Fig. 6a

Tracking On at 16KHz, 4800RPM, use Peak Mirror




Fig. 6b